

FIG. 1

Attorney Docket No.: 1033-IT1003 Inventor(s): Baofeng Frank Jiang, et al. Attorney: Jeffrey G. Toler (512) 327-5515

2/9

- 200 **Real-time ShowRF** X Help View <u>E</u>dit Tools File http://broadband.sbc.com/LPA/showRF?phone=925-828-5182 Address (HOME) Real-time Loop Performance Analyzer (DOC) (It takes about 20 seconds to collect data from the DSLAM. Please be patient) 202 **Run Reports** 925-828-5182 Phone: (format: 925-484-3260 or 9254843260 DSLAM time: 2003-06-20 09:21:10 Customer: 925-828-5182 DSLAM: SNRMCA11H02 ADSL-3-1-11-1 PORT: - 204 Line Attributes (Doc) Code NT VPI NT VCI Line VPI Line VCI Status STATUSNE STATUSFE **ADSLPROF ADSLPROFNM** NORMAL 35 IS-NR **NORMAL** 8 25 **CURPWR** MAXAPLVL Speed (kbps) MAXATTAINBR MINBR MAXBR PWR(dBm) CURBR 20 Downstream 15 384 Downstream 960 384 384 Upstream 13 Upstream 128 128 672 128 ATEN(dB) RELCAP(%) Others **CELLS MINNMR MAXNMR CURNMR** NMR(dB) **TNMR** 55 47 Downstream 10 6 12 42556304 0 Downstream Upstream 30760976 0 41 28 6 18 Upstream 10

FIG. 2

Attorney Docket No.: 1033-IT1003 Inventor(s): Baofeng Frank Jiang, et al. Attorney: Jeffrey G. Toler (512) 327-5515

3/9

300 **Real-time ShowRF** X <u>V</u>iew Tools <u>H</u>elp <u>E</u>dit File Address http://broadband.sbc.com/LPA/showRF?phone+925-828-5182 **Line Analysis** The ADSL line serving phone number 925-828-5182 uses ADSL profile #25. CONFIG During the measurement period of 8 hours and 15 minutes, the line experienced 15 minutes of **DN STREAM** Excessive code violations of errored seconds in the downstream transmission path. **ERRORS UP STREAM ERRORS** During the tast measurement period of 8 hours and 15 minutes the line ran error free in the upstream direction. **DN STREAM** The line is running at the maximum bit rate of 384 kbps. SPEED **UP STREAM** The line is running at the maximum bit rate of 128 kbps. SPEED DN STREAM S/N The line noise margin is 12d8, which is above the target noise margin of 6d8. UP STREAM SAN The line noise margin is 18dB, which is above the target noise margin of 6dB. DN STREAM POWER The line power is 15dBm, which is below the maximum of 20dBm. UP STREAM POWER The line power is 2dBm, which is below the maximum of 13dBm. No pilot tone was detected. PILOT TONE **BRIDGED TAPS** The line appears to have a bridged tap. The tap has no effect on channel bandwidth. Loop length is estimated at 12220 feet of equivalent 26 awg cable. LOOP CROSSTALK No crosstalk was found. INTERFERENCE Single frequency interferers were found at 349 kHz. **DN BURST ERRORS** Burst errors were found at the following date and times: 6-20 6,0. **UP BURST ERRORS** No burst errors were found. TCPAP During the last measurement period of 8 hours and 15 minutes, the line experienced severe TCP/IP THROUGHPUT throughput drop to 50% on worst case.

Attorney Docket No.: 1033-IT1003 Inventor(s): Baofeng Frank Jiang, et al. Attorney: Jeffrey G. Toler (512) 327-5515

4/9

- 400 Real-time ShowRF X <u>V</u>iew Help Tools <u>E</u>dit File **Line Code Violation and Error Seconds** Downstream Line code violation: - 402 7:30 7:15 6:0 5:45 5:30 8:45 8:30 8:15 8:0 7:45 7:0 6:45 6:30 6:15 Time 121 3063 0 307 Value 0 0 2 4 3 0 1:45 1:30 1:15 4:30 3:30 3:15 3:0 2:45 2:30 2:15 2:0 Time 5:15 5:0 4:45 4:15 4:0 3:45 0 0 0 0 0 0 0 Value 0 0 0 0 - 404 **Upstream Line code violation:** 9:15 9:0 8:45 8:15 8:0 7:45 7:30 7:15 7:0 6:45 6:30 6:15 6:0 5:45 5:30 Time 0 0 ٥ 0 0 0 0 0 0 0 0 0 0 Value 3:45 3:30 3:15 3:0 2:45 2:30 2:15 2:0 1:45 1:30 1:15 5:15 4:45 4:30 4:0 5:0 4:15 Time Value 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 - 406 **Downstream Error Seconds:** 8:15 8:0 7:45 7:30 7:15 7:0 6:45 6:30 6:15 6:0 5:45 5:30 9:15 9:0 8:45 Time 56 135 Value 0 0 02 3 3 16 1 0 0 3:0 2:45 2:30 2:15 2:0 1:45 | 1:30 1:15 Time 5:15 5:0 4:45 4:30 4:15 4:0 3:45 3:30 3:15 0 0 0 0 0 0 0 0 0 Value 0 0 408 **Upstream Error Seconds:** 6:15 9:0 8:45 8:15 8:0 7:45 7:30 7:15 7:0 6:45 6:30 6:0 5:45 5:30 9:15 Time 0 0 0 0 0 0 0 0 0 0 0 Value O 0 0 4:30 4:15 4:0 3:45 3:30 3:15 3:0 2:45 2:30 2:15 2:0 1:45 1:30 1:15 5:15 5:0 4:45 Time Value 0 0 0 0 0 0 0 0 Green-Good Yellow-Caution Red-Bad White-unknown or default

(REPLACEMENT SHEET)
Attorney Docket No.: 1033-IT1003
Inventor(s): Baofeng Frank Jiang, et al.
Attorney: Jeffrey G. Toler
(512) 327-5515 5/9

omments		
ile <u>E</u> dit <u>V</u> iew <u>T</u> ools <u>H</u> elp		
$\Rightarrow \Rightarrow x$		
Address		
Please enter comments on line 925-828-5182:		
Phone: 925-828-5182		
UserID: bj2181		
Comments: 506		
There is a burst error on this line at 10:30 AM 6/18/03.		
rw8264 Fri Jun 20 10:34:33 PDT 2003		
	•	▼
Clear Send Comments		
Note: The maximum comment size is 3.5KB. If the size	e exceed	S,
you need to delete the part you don't want.		

(REPLACEMENT SHEET)
Attorney Docket No.: 1033-IT1003
Inventor(s): Baofeng Frank Jiang, et al.
Attorney: Jeffrey G. Toler
(512) 327-5515

6/9

<u>F</u> ile	<u>E</u> dit	<u>V</u> iew	<u>T</u> 00	ls <u>H</u> elp)						
\leftarrow	\Box X							•			
Car	d Selec	cted	602	Card	d Inforr	nation					
rack 2	shelf 1	card 5	002	SIO	currer	t sw vers AB4.184	sta IS-	ite -NR	current equip ADLT-E	sw vers HH3CAB4.1	equip ty ADLT-E
	Inform								****		
	- 604			por		state	vp	VC	dsl tn		
				Port 1 ADS	SL-2-1-5- SL <i>-2-</i> 1-5-1			43 81	925-551- 925-828-		
				Port 3 AD	SL-2-1-5-	3 IS-NR	205 .	44	925-828-	6233	
				Port 4 ADS	SL-2-1-5-	IS-NR	216	195	925-828-	5470	
П	ماماماما	<u> </u>	العما	Z olololo	188888		<u> </u>	المما	200000		0000
	00000	ପ୍ରପ୍ରପ୍ରପ୍ର ପ୍ରପ୍ରପ୍ରପ୍ର		000000					90000X	00000	
	00000	00000	_~	9000	00000		0000	800			00 00 00 0
	00000		- 124	000000							0 0 0 00
	90000	ପ୍ରପ୍ରପ୍ରସ ପ୍ରପ୍ରପ୍ରସ	0	000000	300000				00000		0
	00000	00000		0000	00000			\cdots	00000	00000	
		000000					0000				000
	ତ ତ ତ ଭ ତ ାତାଡ	00 00 00000					0 00	0000	90999 90999		6 0 0 6 0
	00000	99999	0	00000			0000	000	00000	0 0	0
	0000			Releided			0000	000	90000		
610	Po	rt Lege	nd		Ca	rd Leg	end				
0.0	22222	ervice, Ne			NT.	Network	Interfac	ce=	Ex	ender Card	
		of Service		The second secon	<u> </u>	e Termina				Data	
		of Service		ainance	1 1	Termina m Contro				lected	

Attorney Docket No.: 1033-IT1003 Inventor(s): Baofeng Frank Jiang, et al. Attorney: Jeffrey G. Toler (512) 327-5515

7/9




FIG. 7

Attorney Docket No.: 1033-IT1003 Inventor(s): Baofeng Frank Jiang, et al. Attorney: Jeffrey G. Toler (512) 327-5515 8/9 802 RECEIVING A REQUESTED TELEPHONE NUMBER CORRESPONDING TO A DIGITAL SUBSCRIBER LINE ELEMENT MAPPING THE TELEPHONE NUMBER TO A PORT ADDRESS ASSOCIATED WITH 804 NETWORK EQUIPMENT SUPPORTING THE DIGITAL SUBSCRIBER LINE ELEMENT, THE DIGITAL SUBSCRIBER LINE ELEMENT LOCATED REMOTELY FROM THE NETWORK EQUIPMENT 806 SENDING A PROVISIONING STATUS REQUEST TO THE PORT ADDRESS TO INTERROGATE THE DIGITAL SUBSCRIBER LINE ELEMENT 808 COLLECTING REAL-TIME PROVISIONING DATA OF THE DIGITAL SUBSCRIBER LINE ELEMENT IN RESPONSE TO THE INTERROGATION REQUEST 810 CONVERTING THE REAL-TIME PROVISIONING DATA TO ANALYZED PROVISIONING STATUS DATA 812 DISPLAYING THE ANALYZED PROVISIONING STATUS DATA 814 COMMUNICATING THE PORT NUMBER TO A REGIONAL SERVER 816 SENDING A DATA REQUEST FROM THE REGIONAL SERVER TO A NETWORK EQUIPMENT MANAGEMENT SYSTEM COUPLED TO THE NETWORK **EQUIPMENT** 818 OPTIONALLY CREATING A LOG FILE TO RECORD HISTORICAL TROUBLE EVENTS AND COMMENTS. THE LOG FILE ACCESSIBLE TO A PLURALITY OF OPERATIONAL PERSONNEL WORKING GROUPS OPTIONALLY SCHEDULING A ROUTINE TO AUTOMATICALLY POLL A 820 PLURALITY OF PROVISIONING DATA FOR A PLURALITY OF DEPLOYED NETWORK EQUIPMENT TO CROSSCHECK PROVISIONED ASSIGNMENT DATA USED IN CONNECTION WITH THE TELEPHONE NUMBER TO PORT MAPPING WITH FIELD CONFIGURATIONS OF THE DEPLOYED NETWORK

(REPLACEMENT SHEET)

Attorney Docket No.: 1033-IT1003 Inventor(s): Baofeng Frank Jiang, et al. Attorney: Jeffrey G. Toler (512) 327-5515 **9/9**




FIG. 9